

## Denkemiska sammansättningen avvolfram

markera		WB-1	WB-2	WB-3	WB-4	typisk-1	typisk-2
den maximalaförening%	Pb	--	--	--	0.001	--	0.001
	Bi	--	--	--	0.001	--	0.001
	Sn	--	--	--	0.001	--	0.001
	As	--	--	--	0.002	--	0.001
	Fe	0.005	0.005	0.010	0.05	0.005	0.020
	Ni	0.003	0.003	0.005	0.30	0.002	0.005
	Al	0.002	0.002	0.005	0.005	0.001	0.003
	Si	0.003	0.003	0.010	0.010	0.0015	0.002
	Ca	0.003	0.003	0.005	0.005	0.002	0.005
	Mg	0.002	0.002	0.005	0.010	0.001	0.001
	Mo	0.010	0.010	0.20	0.20	0.003	0.050
	P	0.001	0.001	0.002	0.005	0.001	0.001
	C	0.005	0.008	0.010	0.010	0.003	0.003
	O	0.003	0.003	0.005	0.008	0.003	0.008
	N	0.003	0.003	--	--	0.003	--
Sb	--	--	--	0.001	--	0.0005	
använda		volframlegering	materialbearbetning	materialbearbetning	legeringtillsats	materialbearbetning	legeringtillsats

OBS: Alla andraspecifikationer förprodukter enligt kundens önskemål.