

La composizione chimica del tungsteno

segnare	WB-1	WB-2	WB-3	WB-4	tipico -1	tipico -2	
Il massimo di impurità%,	Pb	--	--	--	0.001	--	0.001
	Bi	--	--	--	0.001	--	0.001
	Sn	--	--	--	0.001	--	0.001
	As	--	--	--	0.002	--	0.001
	Fe	0.005	0.005	0.010	0.05	0.005	0.020
	Ni	0.003	0.003	0.005	0.30	0.002	0.005
	Al	0.002	0.002	0.005	0.005	0.001	0.003
	Si	0.003	0.003	0.010	0.010	0.0015	0.002
	Ca	0.003	0.003	0.005	0.005	0.002	0.005
	Mg	0.002	0.002	0.005	0.010	0.001	0.001
	Mo	0.010	0.010	0.20	0.20	0.003	0.050
	P	0.001	0.001	0.002	0.005	0.001	0.001
	C	0.005	0.008	0.010	0.010	0.003	0.003
	O	0.003	0.003	0.005	0.008	0.003	0.008
N	0.003	0.003	--	--	0.003	--	
Sb	--	--	--	0.001	--	0.0005	
utilizzare	tungsteno	materiale Processing	materiale Processing	lega di additivo	materiale Processing	lega di additivo	

Nota: Tutte le altre specifiche dei prodotti in base alle esigenze del cliente.